After downloading program onto computer double click on PC loader file.exe to open

|	Name	Date modified	Type	Size
	A1A_01.hex	2/21/2020 3:09 PM	HEX File	251 KB
☑	PC_loader.exe	9/28/2011 4:45 AM	Application	264 KB
	PC_Loader.zip	5/12/2020 10:56 AM	WinRAR ZIP archive	196 KB

Attach USB- C Cable to A1F USB-C port

Plug Other side of USB cable into

Click on "Enable" Box, Then Click on Connect

Note That the Screen will now show "Device Connected"

Select Erase-Program-Verify Then "Load Hex File"

Note Hex File Loaded Sucessfully

Next Select Disconnect

Note Devise disconnected

Unplug Power Cord and remove USB Cable