## CHEM-FEED®

**Chemical Feed Systems** 

## CPVC Single Skid Shipping Kit

Part No.	Description	Quantity	Picture
90008-437	Tubing - ½" Braided  Comes as 2 pieces of 2.5 ft length. Used to connect pump to skid for ½" tube connection.	5 ft	
90008-043	Clamp - Hose (# 5) Used to clamp ½" tube connections to hose barb fittings.	8	
71000-845	Union - ½" NPT to ½" Hose Barb  Attaches to male NPT pump tube assemblies.	2	
76001-623	Adapter - ½" Slip to ½" Hose Barb  Glue to main inlet and outlet valves of skid.	3	
NOT AVAILABLE	Elbow - ½" MNPT to ½" Hose Barb  Screws into threaded union for connecting C2 and C3 pumps to skid.		
90008-462	Union - ½" Threaded  Screws onto C2 and C3 adapters for ½" tube connection.	2	
76001-627 90008-305	Adapter - ½" Slip to 3/8" OD Tube Glue into skid for 1/4" tube connection to pump. Tube Nut Compresses 1/4" tube to adapters.	2	
76000-296	Tubing - 1/4" ID (3/8" OD)  Connect to calibration cylinder for air release.	5 ft	
73000-161	Threaded Ball Valve Ends Optional threaded ends for ball valves.	3	

Part No.	Description	Quantity	Picture
90008-364 90011-122	Extended Bracket Attached to bottom of pump. Screw 10-32 x .50 Phl. Pan Head Attaches bracket to pump.	2 4	
90011-195	Screw 10-32 x.62 Soc. Head  Mounts pump onto skid using brackets provided.	4	
90011-026	Nut 10-32 Hex Used along with screw #90011-195 to mount pump to skid.	4	
90011-094	Washer #10 Use 2 washers per screw #90011-195 and nut #90011-026 to mount pump to skid.	8	
90008-162	Allen Wrench "5/32" Used on 10-32 screws for mounting pump to skid frame.	1	
90008-249	Allen Wrench "3/16"  Used on 1/4-20 screws for securing/mounting the skid frame.	1	
90008-443	Drip Tray	1	
80000-462	Instruction Manual	1	CHEM-FEED  B Authorises
80000-469	Quality Certificate	1	Controlled in former and speed.  Soft Trees.  The state of the state o
80000-470	Quick Start Guide	1	The state of the s

Note: Instruction sheets that come with calibration column, pressure relief valve, and ball valves should also be included in this shipping kit.