CHEM-FEED®

PVC

Chemical Feed Systems

Chemical Feed Systems

Chem-Pro Pumps
1/2" Female NPT Connections

Dual Skid Shipping Kit

Part No.	Description	Quantity	Picture
90008-437	Tubing - ½" Braided Used to connect pump to skid for ½" tube connection.	2.5 ft x 4	
90008-043	Clamp - Hose (# 5) Used to clamp ½" tube connections to hose barb fittings.	11	
90008-429	Union - ½" Threaded Screws onto C2 and C3 adapters for ½" tube connection.	4	
90008-478	Elbow - ½" MNPT to ½" Hose Barb Screws into threaded union for connecting C2 and C3 pumps to skid.	4	
73000-159	Threaded Ball Valve Ends Optional threaded ends for ball valves.	3	
76001-487	Adapter - ½" Slip to ½" Hose Barb Glue to main inlet and outlet valves of skid.	3	
76000-296	Tubing - 1/4" ID (3/8" OD) -Used with 8, 16 & 32 GPH calibration columns. Connects to calibration cylinder for air release.	5 ft x 1	
76000-171	Tubing - 1/4" OD -Used with 1.6 & 4 GPH calibration columns. Connects to calibration cylinder for air release.	5 ft x 1	
90008-364	Extended Bracket Attached to bottom of pump.	4	

Part No.	Description	Quantity	Picture
90011-122	Screw 10-32 x .50 Phl. Pan Head	8	_
	Attaches bracket to pump.		
90011-195	Screw 10-32 x.62 Soc. Head	8	
	Mounts pump onto skid using brackets provided.		
90011-026	Nut 10-32 Hex	8	
	Used along with screw #90011-195 to mount pump to skid.		
90011-094	Washer #10	16	
	Use 2 washers per screw #90011-195 and nut #90011-026 to mount pump to skid.		
90008-162	Allen Wrench "5/32"	1	
	Used on 10-32 screws for mounting pump to skid frame.		
90008-249	Allen Wrench "3/16"	1	
	Used on 1/4-20 screws for securing/mounting the skid frame.		
90008-443	Drip Tray	2	
80000-462	Instruction Manual	1	CHEM-FEED B Pulleting
80000-469	Quality Certificate	1	GOLVERS to special to later. ***Commission of the commission of t
80000-470	Quick Start Guide	1	

Note: Instruction sheets that come with calibration column, pressure relief valve, and ball valves should also be included in this shipping kit.